Hurlingham School

Date: September 2021

Risk Assessment for Fire on the Putney Bridge Road Site

Reviewed by: Simon Gould, Fiona Goulden, Deputy Heads, Heads of Section & Caretaker

Review on: September 2022

	Activity	Persons at risk	Hazards and Risks	Control to retain level of risk (or reduce it further)	Follow up comments
1	Kitchen	Adults and Children	Fire/injury Burning/smoke	 Emergency gas cut off. Fire shutter over hatch into hall. Two means of escape primary ⇒ door to side passage secondary ⇒ into main hall then garden room doors to playground Fire door to kitchen. Staff who might use gallery over hall/ kitchen must look through windows onto hall for evidence of kitchen fire before using this route if clear. 	
2	Plant rooms	Adults and Children	Fire/explosion	 Fire door. Regular maintenance. Locked shut. 	The plant room on the 2 nd floor has been tidied to ensure no flammable items are near to the boiler.
3	Spread	Adults and Children	Smoke Burning	 Fire officer for each compartment to ensure that all doors in their areas are shut before exiting building. Alarm activated door releases fitted to some fire doors 14.4.20 	
4	Persons left in building	Adults and Children	Injury/death	 All teachers to take form registers to playground for roll call. Fire officers to ensure all rooms in their compartment are clear before exiting the building. Visitors book to be kept up to date and taken into playground by receptionist when alarm sounds. Staff to sign in and out of building at reception ⇒ to playground in front. 	
5	Insufficient evacuation training	Adults and Children	Injury/death	 Minimum of one fire practice each term. Vary location of fire in practices. Ensure fire practices carried out at different times of day on different days of the week. Teachers trained in use of fire extinguishers. 	See Fire Practice Log and staff training booklets